

Badger State Auto Auction

05/05/2022

DRIVE LANE

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
D 0022	Drive Lane (Red)	2003	Ford	F250	RD	118,448		6.0 diese
Transmission/Drive Train: Transmission Problem, Road Test, Shifts Late; Steering System: Needs Repair, Needs Ball Joints								
D 0023	Drive Lane (Red)	2007	Jeep	Grand Cherokee	TL	232115		3.7
Engine Runner: Heavy Oil Leak; Fuel System: Problem; Transmission/Drive Train: Road Test, 4x4 Not-Working; Brake System:Needs Repair, ABS Light On, Brake System/ Tracs Control; Suspension System: Needs Repair, Needs Shocks; Frame/Unibody: Rusted Thru in Spots; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Electrical System: ABS Light On, Check/Service Engine Light On tank straps rusted								
D 0024	Drive Lane (Red)	2003	Chrysler	PT Cruiser GT	BK	141689		2.4
Engine Runner: Runs Rough; Cooling System: Needs Repair, Water pump Leaks; Transmission/Drive Train: Road Test; Brake System:Needs Repair; Suspension System: Needs Repair, Needs Bushings, Noisy Struts; Steering System: Needs Repair, Needs Ball Joints, Needs Wheel Bearings; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Electrical System: Check/Service Engine Light On cracked windshield								
D 0025	Drive Lane (Red)	2000	Toyota	Camry	MR	295,530		3.0
Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Broken Coil Springsright rear spring is broken, left front spring is broken.								
D 0026	Drive Lane (Red)	2005	Land Rover	Freelander	WH	141366		2.5
Engine Runner: Runs Rough; Transmission/Drive Train: Transmission Problem, Road Test; Electrical System: Needs Repair, SRS/Airbag Light On, Check/Service Engine Light On rear diff leak control arms rusted thru								
D 0027	Drive Lane (Red)	2008	Honda	Accord	TA	233,926		2.4
Transmission/Drive Train: Road Test; Frame/Unibody: Legal, Needs Repairl Due to:, Floor Pans; Options: A/C Does Not Work (blows warm), windshield cracked.								
D 0028	Drive Lane (Red)	2002	Ford	Explorer	SI	116114		4.0
Engine Runner: Heavy Oil Leak; Transmission/Drive Train: Road Test; Suspension System: CV Boots Damaged; Steering System: Needs Tie Rods								
D 0029	Drive Lane (Red)	2012	Ford	Fusion	MR	93500		3.0
Transmission/Drive Train: Road Test; Brake System:Needs Repair; Suspension System: Needs Repair, Needs Stabilizer Links								