

Greater Milwaukee Auto Auction

10/14/2021

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
PT0022	Drive Lane (Red)	2001	Honda	Accord	SI	266076		3.0
	Engine Runner: Heavy Oil Leak; Transmission/Drive Train: Yard Driven Only; Brake System: Needs Repair, Pedal Goes to Floor; Suspension System: Needs Bushings, Needs Shocks idle surge							
R40001	Drive Lane (Red)	2007	Ford	Freestyle	BL	130036		3.0
	Transmission/Drive Train: Road Test; Steering System: Needs Repair, Needs Wheel Bearings; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, SRS/Airbag Light On							
R40002	Drive Lane (Blue)	2007	Ford	Taurus	SI	137773		3.0
	Transmission/Drive Train: Road Test							
R40003	Drive Lane (Red)	2004	Chevrolet	Venture	SI	197257		3.4
	Engine Runner: Engine Overheats; Cooling System: Needs Repair, Radiator Leaks, Empty; Transmission/Drive Train: Yard Driven Only; Steering System: Needs Repair, Needs Tie Rods; Frame/Unibody: Needs Repair Due to:; Electrical System: Needs Repair							
R40004	Drive Lane (Red)	2006	Volkswagen	Passat	BK	208341		3.6
	Engine Runner: Runs Rough; Fuel System: Problem; Transmission/Drive Train: Yard Driven Only; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Electrical System: Check/Service Engine Light On							
R40005	Drive Lane (Red)	2006	Chevrolet	Equinox	GY	207521		3.4
	Transmission/Drive Train: Road Test; Brake System: Needs Repair, ABS Light On; Suspension System: Needs Repair, Needs Shocks; Steering System: Needs Repair, Needs Wheel Bearings; Options: Windows Have Electrical Problem							
R40006	Drive Lane (Red)	2004	Chevrolet	Impala	BL	175800		3.4
	Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots							
R40007	Drive Lane (Blue)	2012	Chrysler	200	GY	159337		2.4
	Transmission/Drive Train: Road Test							
R40008	Drive Lane (Blue)	2002	Subaru	Outback	BL	189200		2.5
	Transmission/Drive Train: Road Test							
R40009	Drive Lane (Red)	2003	Honda	Pilot	BK	387952		3.5
	Transmission/Drive Train: Transmission Problem, Road Test; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged; Frame/Unibody: Needs Repair Due to:, Rusted Thru in Spots							
R40010	Drive Lane (Red)	2004	Dodge	Intrepid	SI	87115		2.7
	Transmission/Drive Train: Road Test; Exhaust: Manifold Leaking, Muffler; Electrical System: Check/Service Engine Light On; Options: A/C Does Not Work (compressor does not engage), Windows Have Electrical Problem							
R40011	Drive Lane (Red)	2001	Ford	Explorer	MR	168949		4.0
	Transmission/Drive Train: Road Test; Exhaust: Manifold Leaking							

R40012	Drive Lane (Red)	1993	Ford	F150	GN	191148	5.0
	Cooling System: Needs Repair, Water pump Leaks; Transmission/Drive Train: Need U Joint, Needs U Joints, Yard Driven Only; Suspension System: Needs Repair, Needs Bushings, Rusted Strut Towers, Needs Shocks; Frame/Unibody: Legal, Rocker Panels Rusted Thru, Rusted Thru in Spots, Structural Damage						
R40013	Drive Lane (Red)	2000	Toyota	Solara	RD	199869	3.0
	Engine Runner: Heavy Oil Leak, Rear Main Seal Leak; Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Bushings; Steering System: Needs Tie Rods; Frame/Unibody: Rocker Panels Rusted Thru						
R40014	Drive Lane (Red)	2010	Mazda	Mazda6i	SI	240316	2.5
	Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Repair, Needs Shocks; Steering System: Needs Repair, Needs Tie Rods, Needs Ball Joints, Needs Wheel Bearings; Frame/Unibody: Needs Repair; Due to::; Electrical System: Needs Repair, Check/Service Engine Light On						
R40015	Drive Lane (Red)	2007	Chrysler	300	MR	145213	3.5
	Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, ABS Light On, Brake System/ Tracs Control; Suspension System: Needs Repair, Needs Stabilizer Links, Needs Shocks; Steering System: Needs Ball Joints needs sway bar						
R40016	Drive Lane (Red)	2013	Dodge	Grand Caravan	BL	105631	3.6
	Transmission/Drive Train: Road Test; Brake System:Needs Repair; Suspension System: Needs Stabilizer Links						
R40017	Drive Lane (Red)	2000	Honda	CRV	GN	113,192	2.0
	Transmission/Drive Train: Road Test; Frame/Unibody: Legal; Electrical System: Check/Service Engine Light On; Options: Power Mirrors Not Working						
R40018	Drive Lane (Red)	2001	GMC	Sierra 1500	BG	242672	5.3
	Engine Runner: Runs Rough; Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, ABS Light On, Pedal Goes to Floor, Brake System/ Brake Line Leaks; Suspension System: Needs Bushings; Frame/Unibody: Rocker Panels Rusted Thru; Electrical System: Needs Repair, Check/Service Engine Light On						
R40019	Drive Lane (Blue)	2006	Chrysler	PT Cruiser	BK	128478	2.4
	Transmission/Drive Train: Road Test						
R40020	Drive Lane (Red)	2004	Toyota	Camry	WH	247795	2.4
	Transmission/Drive Train: Yard Driven Only; Steering System: Needs Repair, Bad Rack & Pinion						