

### Greater Milwaukee Auto Auction

**11/23/2021**

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
R40001	Drive Lane (Red)	2010	Subaru	Forester	GY	181418		2.5
Engine Runner: Engine Overheats, Runs Rough; Cooling System: Needs Repair, Radiator Leaks, Empty; Transmission/Drive Train: Yard Driven Only								
R40002	Drive Lane (Red)	2004	Chevrolet	Trailblazer	GN	144834		4.2
Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair Due to:								
R40004	Drive Lane (Red)	2007	Nissan	Altima	GN	209752		2.5
Engine Runner: Heavy Oil Leak; Brake System:Needs Repair; Exhaust: Needs Hangers/Clamps; Suspension System: Needs Repair, Needs Bushings, Needs Stabilizer Links, Noisy Struts, Needs Shocks; Steering System: Needs Repair, Needs Wheel Bearings								
R40005	Drive Lane (Red)	1990	Mercedes	300D	WH	310432		2.5
Engine Runner: Runs Rough; Transmission/Drive Train: Road Test								
R40006	Drive Lane (Red)	2000	Buick	LeSabre	BL	123744		3.8
Engine Runner: Heavy Oil Leak; Brake System:Needs Repair; Frame/Unibody: Rusted Thru in Spots, Floor Pansbraks pulsate								
R40007	Drive Lane (Red)	2006	Toyota	Avalon	BG	259,521		3.5
Transmission/Drive Train: Road Test; Frame/Unibody: Legal; Options: Windows Have Electrical Problemright front window inoperative from the drivers switch. oil leaks								
R40008	Drive Lane (Red)	2008	Acura	TL Type S	BK	156785		3.5
Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Bushings, Needs Stabilizer Links; Electrical System: Needs Repair, Check/Service Engine Light On								
R40009	Drive Lane (Red)	2004	Chevrolet	Silverado 3500	WH	230070		6.6
Engine Runner: Engine Problem, Runs Rough, Heavy Oil Leak; Fuel System: Problem; Transmission/Drive Train: Road Test, Needs U Joints; Brake System:Needs Repair, ABS Light On; Exhaust: Needs Hangers/Clamps; Frame/Unibody: Rusted Thru in Spots, Rocker Panels Rusted Thru, Collision Damage; Electrical System: ABS Light On								
R40010	Drive Lane (Red)	2004	Buick	Regal	SI	94954		3.8
Transmission/Drive Train: Road Test								
R40011	Drive Lane (Red)	2008	Ford	Focus	BL	181877		2.0
Engine Runner: Runs Rough; Transmission/Drive Train: Road Test								
R40012	Drive Lane (Blue)	2008	Chrysler	Sebring	SI	174429		2.7
Transmission/Drive Train: Road Test								

R40013	Drive Lane (Red)	2003	Jeep	Grand Cherokee	GY	126873	4.0
	Transmission/Drive Train: Road Test; Brake System: ABS Light On; Suspension System: Needs Repair, Needs Stabilizer Links; Steering System: Needs Repair						
R40014	Drive Lane (Red)	1997	Honda	Civic	WH		1.8
	Transmission/Drive Train: Road Test; Electrical System: Check/Service Engine Light On						
R40015	Drive Lane (Blue)	1999	Honda	Odyssey EX	GN	126721	3.5
	Transmission/Drive Train: Road Test						
R40016	Drive Lane (Blue)	1999	Chevrolet	Suburban K1500	TA	246907	5.7
	Transmission/Drive Train: Road Test						
R40017	Drive Lane (Blue)	2006	Hyundai	Sonata	GY	155998	3.3
	Transmission/Drive Train: Road Test						
R40018	Drive Lane (Red)	2000	Mercury	Sable	BL	178214	3.0
	Transmission/Drive Train: Transmission Problem, Does Not Go Into Gear						
R40019	Drive Lane (Red)	2000	Toyota	Camry	GY	174525	2.2
	Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Tailpipe, Gaskets/Donuts Worn, Needs Hangers/Clamps, Muffler; Suspension System: Needs Repair, Broken Coil Springs, Noisy Struts; Steering System: Needs Repair, Needs Tie Rods; Options: A/C Does Not Work (compressor does not engage)						
R40020	Drive Lane (Red)	2009	Chevrolet	Express 1500	WH	152399	5.3
	Transmission/Drive Train: Road Test; Frame/Unibody: Needs Repair! Due to:, Rusted Thru in Spots						