

Badger State Auto Auction

01/13/2022

CERTIFIED REPAIRABLE

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
V 0001	Cert Repair (Red) No Guarantee/As Is Electrical System: Check/Service Engine Light On	2008	Mazda	3	SI	209201		2.3
V 0002	Cert Repair (Red) No Guarantee/As Is Engine Runner: Engine Overheats; Cooling System: Empty; Electrical System: Needs Repair	2004	Honda	Civic	SI	210304		1.7
V 0003	Cert Repair (Red) No Guarantee/As Is Engine Runner: Engine Problem, Engine Overheats, Runs Rough, Heavy Oil Leak; Cooling System: Needs Repair, Water pump Leaks, Empty; Transmission/Drive Train: Yard Driven Only; Electrical System: Needs Repair, Check/Service Engine Light On	2002	GMC	Envoy	WH	204722		4.2
V 0004	Cert Repair (Red) No Guarantee/As Is Fuel System: Problem, Line Leaks; Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Repair, Needs Shocks	2007	Subaru	Impreza	GN	157047		2.5
V 0005	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Transmission Problem, Does Not Go Into Gear	1994	Honda	Accord	GN	126700		2.2
V 0006	Cert Repair (Red) No Guarantee/As Is Brake System:Needs Repair, Pedal Goes to Floor; Suspension System: Needs Repair, Needs Stabilizer Links; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots	2002	Chevrolet	Silverado 1500	BK	164067		5.3
V 0007	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test	2005	Nissan	Titan	RD	164171		5.6
V 0008	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test, Disassembled	2005	Toyota	Camry	RD	079056		2.4
V 0009	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Electrical System: Ignition Has Security Issue	2005	Chevrolet	Uplander	BL	169348		3.5
V 0010	Cert Repair (Red) No Guarantee/As Is Steering System: Needs Repair, Bad Rack & Pinion; Frame/Unibody: Needs Repairl Due to:, Noticeable Repairs	2012	Chevrolet	Silverado	RD	198429		5.3
V 0011	Drive Lane (Red) Transmission/Drive Train: Road Test; Brake System:Needs Repair; Steering System: Needs Repair, Power Steering Box Leaks, Steering Rack Leaks	2012	Dodge	Grand Caravan	BL	173319		3.6

V 0012	Drive Lane (Red)	2004	Chevrolet	Malibu	RD	288153	3.5
Engine Runner: Heavy Oil Leak; Transmission/Drive Train: Road Test; Brake System:Needs Repair; Exhaust: Gaskets/Donuts Worn; Suspension System: Needs Shocks brakes pulsate							
V 0013	Cert Repair (Red) No Guarantee/As Is	2010	Toyota	Prius	BK	276100	1.8
Cooling System: Needs Repair, Radiator Leaks, Empty; Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair; Suspension System: Noisy Struts; Frame/Unibody: Rusted Thru in Spots; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Electrical System: Check/Service Engine Light On hybrid cooling system fault							
V 0014	Cert Repair (Red) No Guarantee/As Is	2000	BMW	328i	BK	192816	2.8
Engine Runner: Runs Rough, Heavy Oil Leak; Cooling System: Needs Repair, Radiator Leaks, Empty; Transmission/Drive Train: Yard Driven Only							
V 0015	Drive Lane (Red)	1999	Volkswagen	New Beetle	YE	135961	2.0
Engine Runner: Heavy Oil Leak; Transmission/Drive Train: Road Test; Brake System: ABS Light On; Exhaust System: Needs Repair; Exhaust: Needs Hangers/Clamps; Suspension System: Needs Shocks; Frame/Unibody: Rusted Thru in Spots, Floor Pans; Electrical System : Wiring Damaged; Electrical System: ABS Light On							