

Greater Milwaukee Auto Auction

01/13/2022

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
R40001	Drive Lane (Red)	2013	Jeep	Patriot	BK	96608		2.4
	Transmission/Drive Train: Road Test; Brake System:Needs Repair, Pedal Goes to Floor; Electrical System: Needs Repair							
R40002	Drive Lane (Red)	2012	Ford	Focus	WH	98,471		2.0
	, wipers inop. horn inop							
R40003	Drive Lane (Blue)	2005	Ford	500	GY	71,271		3.0
	Transmission/Drive Train: Road Test; Frame/Unibody: Legal							
R40004	Drive Lane (Red)	2011	Kia	RIO	WH	146593		1.6
	Transmission/Drive Train: Road Test, Needs TPM's							
R40005	Drive Lane (Red)	2005	Chevrolet	Equinox LS	GY	95307		3.4
	Cooling System: Needs Repair, Empty							
R40006	Drive Lane (Red)	2010	Honda	Fit	BL	146667		1.5
	Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Stabilizer Links, Noisy Struts, Needs Shocks needs tires							
R40007	Drive Lane (Red)	2007	Ford	Focus	WH	166181		2.0
	Transmission/Drive Train: Road Test; Electrical System: Check/Service Engine Light On							
R40008	Drive Lane (Red)	2004	Jeep	Grand Cherokee	RD	281547		4.0
	Engine Runner: Runs Rough; Brake System:Needs Repair; Electrical System: Check/Service Engine Light On							
R40009	Drive Lane (Red)	2003	Toyota	Highlander	GY	219027		3.0
	Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Bushings, Needs Stabilizer Links, Rusted Strut Towers							
R40010	Drive Lane (Red)	2002	Chevrolet	Prizm	BL	103452	I	1.8
	Transmission/Drive Train: Road Test, Brake lite on							
R40011	Drive Lane (Red)	2002	Buick	Century	WH	168398		3.1
	Engine Runner: Heavy Oil Leak; Transmission/Drive Train: Road Test; Frame/Unibody: Rocker Panels Rusted Thru							
R40012	Drive Lane (Red)	2009	Chevrolet	Impala	BL	177,258		3.9
	Transmission/Drive Train: Road Test; Frame/Unibody: Legal; Options: A/C Does Not Work (compressor does not engage)							

R40013	Drive Lane (Red)	2005	Chevrolet	Equinox	RD	148284	3.4
	Engine Runner: Runs Rough; Transmission/Drive Train: Road Test; Suspension System: Broken Coil Springs, Needs Stabilizer Links; Steering System: Needs Wheel Bearings; Frame/Unibody: Rocker Panels Rusted Thru; Electrical System: Check/Service Engine Light On						
R40014	Drive Lane (Red)	2000	Toyota	Avalon	BK	179,565	3.0
	Transmission/Drive Train: Road Test; Suspension System: Needs Stabilizer Links; Frame/Unibody: Legal						
R40015	Drive Lane (Red)	2000	Chevrolet	Silverado 1500	SI	77902	5.3
	Transmission/Drive Train: Road Test; Brake System:Needs Repair; Suspension System: Needs Repair, Needs Shocks; Steering System: Needs Repair; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots brake pulsation						
R40016	Drive Lane (Red)	2003	Chevrolet	Suburban	MR	205,060	5.3
	Transmission/Drive Train: Road Test; Suspension System: Damaged Body Mounts; Frame/Unibody: Legal; Options: A/C Does Not Work (compressor does not engage)						
R40017	Drive Lane (Red)	2005	Chrysler	Town & Country	GN	127075	3.8
	Engine Runner: Heavy Oil Leak; Transmission/Drive Train: Road Test; Brake System:Needs Repair, ABS Light On; Suspension System: Needs Bushings; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots; Electrical System: Needs Repair; Electrical System : Wiring Damagedgas gauge inaccurate						
R40018	Drive Lane (Red)	2005	Mercury	Montego	SI	129,907	3.0
	Transmission/Drive Train: Road Test; Options: Windows Have Electrical Problem						
R40019	Drive Lane (Red)	2007	Toyota	Camry	GY	176596	2.4
	Transmission/Drive Train: Road Test; Frame/Unibody: Legal, Collision Damage; Electrical System: Needs Repair; Electrical System : Wiring Damaged						
R40020	Drive Lane (Red)	2009	Volvo	XC90	SI	175737	3.2
	Engine Runner: Runs Rough; Transmission/Drive Train: Road Test; Exhaust: Needs Hangers/Clamps; Suspension System: Needs Bushingsstutters on accel						
R40021	Drive Lane (Red)	2004	Hyundai	Santa Fe GLS	SI	148490	2.7
	Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Gaskets/Donuts Worn; Frame/Unibody: Rocker Panels Rusted Thru						
R40022	Drive Lane (Red)	1998	Chevrolet	Astro	GN	138566	4.3
	Transmission/Drive Train: Road Test; Exhaust: Gaskets/Donuts Worn; Suspension System: Noisy Struts, Needs Shocks; Frame/Unibody: Rocker Panels Rusted Thru, Rusted Thru in Spots; Electrical System: Needs Repair; Electrical System : Wiring Damaged						
R40023	Drive Lane (Red)	1998	Buick	Century	BL	47,423	3.1
	Transmission/Drive Train: Road Test; Frame/Unibody: Legal; Options: A/C Does Not Work (blows warm)						
R40024	Drive Lane (Blue)	2006	Toyota	Prius	RD	151139	1.5
	Transmission/Drive Train: Road Test						
R40025	Drive Lane (Red)	1993	Ford	Ranger	TL	50323	4.0
	Transmission/Drive Train: Road Test; Suspension System: Needs Repair; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots						