

Badger State Auto Auction 05/05/2022

CERTIFIED REPAIRABLE

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
V 0001	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test, Disassembled; Electrical System: Needs Repair	2011	Hyundai	Sante Fe	BK	121530		
V 0002	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, Pedal Goes to Floor, Brake System/ Brake Line Leaks; Suspension System: Needs Repair, Needs Stabilizer Links; Steering System: Needs Repair, Needs Tie Rods; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots	1999	Buick	Regal	MR	112537		3.8
V 0003	Cert Repair (Red) No Guarantee/As Is Fuel System: Problem; Cooling System: Needs Repair, Water pump Leaks; Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair; Steering System: Needs Repair, Needs Tie Rods; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots; Electrical System: Needs Repair, SRS/Airbag Light On	2006	Dodge	Ram	RD	155749		5.7
V 0004	Cert Repair (Red) No Guarantee/As Is Cooling System: Needs Repair, Radiator Leaks, Empty; Transmission/Drive Train: Road Test; Electrical System: Needs Repair, Check/Service Engine Light On	1992	Ford	E150	BK	179549		5.8
V 0005	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Transmission Problem; Brake System:Needs Repair, ABS Light On; Steering System: Needs Repair, Needs Ball Joints; Electrical System: Needs Repair, Check/Service Engine Light On	2004	Lexus	GS300	BK	156794		3.0
V 0006	Cert Repair (Red) No Guarantee/As Is Engine Runner: Engine Problem, Runs Rough; Transmission/Drive Train: Transmission Problem, Slips, Shifts Hard Into Gear, Shifts Late, Yard Driven Only; Exhaust System: Needs Repair; Exhaust: Needs Hangers/Clamps, Muffler; Suspension System: Needs Repair, Needs Shocks; Steering System: Needs Repair, Power Steering Box Leaks	2000	Nissan	Frontier	MR	151677		3.3
V 0007	Drive Lane (Red) Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Gaskets/Donuts Worn; Suspension System: Needs Repair, Needs Stabilizer Links, Needs Shocks; Frame/Unibody: Needs Repairl Due to:, Rusted Thru in Spots; Options: A/C Does Not Work (blows warm)	2005	Mazda	Tribute	GY	85,578		3.0
V 0008	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test, Seized, oil seep	2015	Hyundai	Santa Fe	CO	74257		2.4
V 0009	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Transmission Problem, Slips, Does Not Go Into Gear; Suspension System: Needs Repair, Needs Stabilizer Links; Frame/Unibody: Legal; Options: A/C Does Not Work (blows warm)	2000	Lexus	ES 300	SI	172,921		3.0