

Badger State Auto Auction

05/26/2022

CERTIFIED REPAIRABLE

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
V 0001	Cert Repair (Red) No Guarantee/As Is Engine Runner: Engine Overheats; Cooling System: Needs Repair, Empty; Transmission/Drive Train: Yard Driven Only; Suspension System: Needs Repair; Electrical System: Check/Service Engine Light On, Alternator Needs Replacingneeds tires	2004	Audi	A8 L	SI	220603		4.2
V 0002	Cert Repair (Red) No Guarantee/As Is Engine Non-runner: Unable to Test	2004	Honda	Pilot	GN	272235		3.5
V 0003	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair; Suspension System: Needs Repair, Needs Stabilizer Links; Steering System: Needs Repair, Needs Tie Rods	2003	Toyota	Camry	BK	292626		2.4
V 0004	Cert Repair (Red) No Guarantee/As Is Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, ABS Light On, Pedal Goes to Floor, Brake System/ Brake Line Leaks; Suspension System: Needs Shocks; Electrical System: Needs Repair; Electrical System : Wiring Damaged; Electrical System: Alternator Needs Replacing	2002	Ford	Ranger	BL	183347		4.0

4

DRIVE LANE

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
D 0010	Drive Lane (Red) Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Broken Coil Springs, Needs Stabilizer Links; Frame/Unibody: Legal; Options: Power Mirrors Not Working, left power mirror inop. right front spring broken.	2008	Toyota	Sienna	WH	291,324		3.5

1