

Greater Milwaukee Auto Auction

05/26/2022

<u>Run#</u>	<u>Certification</u>	<u>Year</u>	<u>Make</u>	<u>Model</u>	<u>Color</u>	<u>Rawhide Check-In Mileage</u>	<u>Title Brand</u>	<u>Engine</u>
R40001	Drive Lane (Red)	1984	Porsche	944	BU	19,589		2.5L
	Transmission/Drive Train: Road Test; Frame/Unibody: Legal; Options: A/C Does Not Work (compressor does not engage)							
R40002	Drive Lane (Red)	2005	Volvo	XC 90	SI	230764		4.4
	Transmission/Drive Train: Transmission Problem, Yard Driven Only; Electrical System: Needs Repair							
R40003	Drive Lane (Red)	2006	Toyota	Sienna	WH	381195		3.3
	Transmission/Drive Train: Road Test; Suspension System: Needs Repair, Needs Bushings, Needs Shocks; Steering System: Needs Repair steering pump worn							
R40004	Drive Lane (Red)	2006	Saturn	Vue	BL	120141		3.5
	Transmission/Drive Train: Road Test; Brake System: Needs Repair; Suspension System: Needs Repair, Needs Bushings, Noisy Struts, Needs Shocks; Steering System: Needs Wheel Bearings; Frame/Unibody: Rocker Panels Rusted Thru; Electrical System: Needs Repair							
R40005	Drive Lane (Red)	2008	Ford	E250	WH	103182		4.6
	Transmission/Drive Train: Road Test; Exhaust: Catalytic Missing; Electrical System: Check/Service Engine Light On							
R40006	Drive Lane (Red)	2006	Ford	E250	WH	100393		5.4
	Transmission/Drive Train: Road Test; Brake System: ABS Light On; Exhaust: Catalytic Missing; Electrical System: Check/Service Engine Light On							
R40007	Drive Lane (Red)	2011	Ford	E250	WH	194013		4.6
	Transmission/Drive Train: Road Test; Exhaust System: Needs Repair; Exhaust: Catalytic Missing; Electrical System: Needs Repair, Check/Service Engine Light On							
R40008	Drive Lane (Red)	2008	Ford	E250	WH	142067		4.6
	Transmission/Drive Train: Road Test; Brake System: ABS Light On; Exhaust System: Needs Repair; Exhaust: Catalytic Missing; Electrical System: Check/Service Engine Light On							
R40009	Drive Lane (Red)	2003	Ford	E250	WH	106583		5.4
	Transmission/Drive Train: Road Test; Exhaust: Catalytic Missing; Electrical System: Check/Service Engine Light On							
R40010	Drive Lane (Blue)	2008	Chevrolet	Express 3500	WH	244069		6.0
	Transmission/Drive Train: Road Test							
R40011	Drive Lane (Red)	2008	Kia	Optima EX	SI	259127		2.4
	Engine Runner: Runs Rough; Transmission/Drive Train: Yard Driven Only; Brake System: Needs Repair, ABS Light On; Electrical System: Needs Repair, Check/Service Engine Light On, Alternator Needs Replacing							

R40012	Drive Lane (Red)	2002	Honda	Civic	SI	129928	1.7
Transmission/Drive Train: Yard Driven Only; Brake System:Needs Repair, ABS Light On, Pedal Goes to Floor; Exhaust System: Needs Repair; Exhaust: Y/Flex Pipe Damaged, Manifold Leaking, Tailpipe, Gaskets/Donuts Worn, Needs Hangers/Clamps, Muffler; Electrical System: Needs Repair, Check/Service Engine Light On; Options: A/C Does Not Work (compressor does not engage), Windows Have Electrical Problem							
R40013	Drive Lane (Red)	2008	Chevrolet	1500 Express	WH	185547	4.3
Transmission/Drive Train: Road Test; Need Blower Motor							
R40014	Drive Lane (Red)	2006	Cadillac	SRX	SI	143619	3.6
Transmission/Drive Train: Road Test; Options: A/C Does Not Work (compressor does not engage)							